

STRUCTURAL STABILITY CERTIFICATE

I have inspected the building in **S.No.: 231, 232**, situated at south bye pass road, pelluru village, Ongole **Municipal Corporation** at each stage of construction and the building was completed with R.C.C. Roof **Ground, First, Second & Third Floors** building and a height of **15.21** meters as per sanctioned plan B.A. NO: **1035/0015/B/ONG/PLRU/2016** dated 20-05-2016 and certified that the completed building is structurally safe and the construction is in accordance with the specified designs.

Date: 10/02/2023



Signature

S.V. Suresh Kumar, B.E.(CIV)
STRUCTURAL ENGINEER
Licence No. 1/2011
Opp: Vijaya Bank,
DHARAVARI THOTA, ONGOLE.